

## Appendix A - References

### 1. DESIGN DOCUMENTS:

- 1.1. Three Rivers Levee Improvement Authority, Bear River, WPIC, & Yuba River Levees Repair Project (Phase 2), Final Basis of Design Report, Project No. 201064-19703-141, December 2006.
- 1.2. Three Rivers Levee Improvement Authority, Yuba River Levees Repair Project, Phase 4, Backcheck Basis of Design, Project No. 201064-36522-141, December 2006.

### 2. PLANNING DOCUMENTS:

- 2.1. Problem Identification Report, Bear River North Levee and the Western Pacific Interceptor Canal West Levee, Reclamation District 784, Yuba County, California, (PIR), November 14, 2003 (revised May 7, 2004), prepared by Kleinfelder, Inc.
- 2.2. Report on Feasibility of RD 784 Supplemental Flood Control Improvements, Flood Control Study Team, October 2004.
- 2.3. Problem Identification Report, Yuba River Left Bank, Highway 70 to SPRR, Reclamation District 784, Yuba County, California, (PIR), June 11, 2004, prepared by Kleinfelder, Inc.
- 2.4. "Problem Identification Report, Yuba River Left Bank Levee SPRR to Simpson Lane (Approximate PLM 0.9 to 2.2), Reclamation District 784, Yuba County, California," (PIR) completed by Kleinfelder, Inc. (August 29, 2005).
- 2.5. "Problem Identification Report, Yuba River Left Bank Levee, Highway 70 to SPRR ( Approximate PLM 0.32 to 0.91), Reclamation District 784, Yuba County, California," dated June 11, 2004. File No. 43299, prepared for Three Rivers Levee Improvement Authority.

### 3. CONSTRUCTION DOCUMENTS:

- 3.1. Three Rivers Levee Improvement Authority, Yuba River Levee Repair Project, Specifications Issued for Construction, Project No. 201064-15116-141, August 2004.

- 3.2. Yuba River Levee Repair Project, Three Rivers Levee Improvement Authority, Linda, California, Drawings Issued for Construction, August 19, 2004, Contract No. CON0005206, HDR Project No. 201064-15116-141.
- 3.3. Three Rivers Levee Improvement Authority, Bear River, WPIC & Yuba River Levees Repair Project, Conformed Technical Specifications Issued for Construction, Project No. 201064-19703-141, August 2005.
- 3.4. Phase II Levee Repairs, Upper Bear River, WP Interceptor Canal and Yuba River, Reclamation District 784, Marysville, CA, Drawings – Issued for Construction, May 18, 2005.
- 3.5. Three Rivers Levee Improvement Authority, Yuba River Levee Repair Project, Phase 4, Conformed, Technical Specifications Issued for Construction, Project No. 201064-36522-141, August 2006.
- 3.6. Three Rivers Levee Improvement Authority, Reclamation District No. 784, Yuba County, CA, Yuba River Levee Repair Project, Phase IV, Conformed Drawings – Issued for Construction, August 31, 2006.
- 3.7. Phase II Levee Repairs, Upper Bear River, WP Interceptor Canal and Yuba River, Yuba County, California, South Olivehurst Pump Station Improvement Plans, Volume I, II & III Drawings – Issued for Construction, July 21, 2005.

#### 4. LABORATORY AND FIELD TEST DATA

- 4.1. FEMA Certification – Construction, Three River Levee Improvements, Reclamation District 784, TRLIA, Yuba County, California, January 24, 2007, Volume I.
- 4.2. FEMA Certification – Construction, Three River Levee Improvements, Reclamation District 784, TRLIA, Yuba County, California, January 24, 2007, Volume II.
- 4.3. FEMA Certification – Construction, Three River Levee Improvements, Reclamation District 784, TRLIA, Yuba County, California, January 24, 2007, Volume III.
- 4.4. Contractor Quality Control Laboratory and Field Testing, For Three Rivers Levee Improvement Authority, Yuba River Levee Repair Project, Marysville, California, Project No. 201064-15116-141, November 29, 2004.
- 4.5. Section 02331A, Quality Control Test Reports, Final Field Compaction Test Report, WPIC Levee Embankment, For South Olivehurst Detention Basin, Bear

- River, WPIC, & Yuba River Levee Repair Project, Marysville, California, Contract No. PH2-2005/06-01, January 22, 2007.
- 4.6. Section 02331A, Quality Control Test Reports, Final Field Compaction Test Report, Bear River Levee and Pump Station No. 6, For South Olivehurst Detention Basin, Bear River, WPIC, & Yuba River Levee Repair Project, Marysville, California, Contract No. PH2-2005/06-01, January 22, 2007.
  - 4.7. Section 02331A, Quality Control Test Reports, Final Laboratory Test Report, Bear River Levee and Pump Station No. 6, For South Olivehurst Detention Basin, Bear River, WPIC, & Yuba River Levee Repair Project, Marysville, California, Contract No. PH2-2005/06-01, January 22, 2007.
  - 4.8. Section 02331A, Quality Control Test Reports, Final Field Compaction Test Report, Yuba River Seepage Berm, For South Olivehurst Detention Basin, Bear River, WPIC, & Yuba River Levee Repair Project, Marysville, California, Contract No. PH2-2005/06-01, January 22, 2007.
  - 4.9. Section 02331A, Quality Control Test Reports, Final Laboratory Test Report, Yuba River Seepage Berm, For South Olivehurst Detention Basin, Bear River, WPIC, & Yuba River Levee Repair Project, Marysville, California, Contract No. PH2-2005/06-01, January 22, 2007.
  - 4.10. Section 02331A, Quality Control Test Reports, Final Laboratory Test Report, WPIC Levee Embankment, For South Olivehurst Detention Basin, Bear River, WPIC, & Yuba River Levee Repair Project, Marysville, California, Contract No. PH2-2005/06-01, January 22, 2007.
  - 4.11. Section 02261A, Quality Control Test Reports, Final Report, WPIC Slurry Wall, For South Olivehurst Detention Basin, Bear River, WPIC, & Yuba River Levee Repair Project, Marysville, California, Contract No. PH2-2005/06-01, January 22, 2007.
  - 4.12. Section 02331A, Quality Control Test Reports, Final Laboratory Test Report, WPIC Levee Embankment, For South Olivehurst Detention Basin, Bear River, WPIC, & Yuba River Levee Repair Project, Marysville, California, Contract No. PH2-2005/06-01, January 22, 2007.
  - 4.13. Section 02331A, Quality Control Test Reports, Final Laboratory Test Report, South Olivehurst Detention Basin Pump Station & Ring Levee, For South Olivehurst Detention Basin, Bear River, WPIC, & Yuba River Levee Repair Project, Marysville, California, Contract No. PH2-2005/06-01, January 22, 2007.
  - 4.14. Section 02331A, Quality Control Test Reports, Final Field Compaction Test Report, South Olivehurst Detention Basin Pump Station & Ring Levee, For South

Olivehurst Detention Basin, Bear River, WPIC, & Yuba River Levee Repair Project, Marysville, California, Contract No. PH2-2005/06-01, January 22, 2007.

- 4.15. Section 03300, Quality Control Test Reports, Final Laboratory Concrete Compression Test Report, South Olivehurst Pump Station & Bear River Pump Station No. 6, For South Olivehurst Detention Basin, Bear River, WPIC, & Yuba River Levee Repair Project, Marysville, California, Contract No. PH2-2005/06-01, January 22, 2007.
- 4.16. Technical Specifications, Section 02261 – Slurry Cutoff Wall, Volume I, As-Built Field and Laboratory Test Data, Three Rivers Levee Improvement Authority, Yuba River Levee Repair Project, Phase 4, Marysville, California, Project No. 201064-36522-141, January 18, 2007.
- 4.17. Technical Specifications, Section 02261 – Slurry Cutoff Wall, Volume II, As-Built Field and Laboratory Test Data, Three Rivers Levee Improvement Authority, Yuba River Levee Repair Project, Phase 4, Marysville, California, Project No. 201064-36522-141, January 18, 2007
- 4.18. Technical Specifications, Section 02331 – Earthwork, As-Built Field and Laboratory Test Data, Three Rivers Levee Improvement Authority, Yuba River Levee Repair Project, Phase 4, Marysville, California, Project No. 201064-36522-141, January 18, 2007

## 5. GENERAL REFERENCES

- 5.1. Construction Contract Administration and Construction Observation, HDR Engineering, Inc., October 2003.